

Inspection Photos
Location Name:HSR-TR Ranch 16-3
Location ID:320407



Photo#1 Production tank ad Produced Water Pit



Photo#2 Separator and Gas Meter

Inspection Photos
Location Name:HSR-TR Ranch 16-3
Location ID:320407



Photo#3 Wellhead

