

**Inspection Photo**  
**Rose Ranch 14-8C**  
**API # 045-08203**  
**Inspection # 689302026**



**Location Photo #1**



**Location Photo #2**

**Inspection Photo  
Rose Ranch 14-8C  
API # 045-08203  
Inspection # 689302026**



**Location Photo #3, Holes in North battery liner.**



**Location Photo #4, Unmarked deadman.**

**Inspection Photo  
Rose Ranch 14-8C  
API # 045-08203  
Inspection # 689302026**



**Location Photo #5, unmarked deadman.**



**Location Photo #6, unmarked deadman.**