

Inspection Photo
Roles 13-14B
API # 045-10056
Inspection # 689302036



Location Photo #1



Location Photo #2

Inspection Photo
Roles 13-14B
API # 045-10056
Inspection # 689302036



Location Photo #3, holes in secondary containment liner.



Location Photo #4, holes in secondary containment liner.

Inspection Photo
Roles 13-14B
API # 045-10056
Inspection # 689302036



**Location Photo #5, holes in secondary
containment liner.**