

Inspection Photo
Roles 13-10
API # 045-06953
Inspection # 689302038



Location Photo #1



Location Photo #2



**Inspection Photo
Roles 13-10
API # 045-06953
Inspection # 689302038**



Location Photo #3



**Location Photo #4, holes in secondary
containment liner.**

Inspection Photo
Roles 13-10
API # 045-06953
Inspection # 689302038



Location Photo #5, holes in secondary containment liner.



Location Photo #6, sediment being moved off location.

Inspection Photo
Roles 13-10
API # 045-06953
Inspection # 689302038



Location Photo #7, sediment being moved off location.



Location Photo #8, sediment being moved on location.

Inspection Photo
Roles 13-10
API # 045-06953
Inspection # 689302038



Location Photo #9, sediment being moved on location.