

Final Reclamation Inspection

September 28, 2018

Operator: WELLINGTON OPERATING COMPANY - 95233

API: 05-069-05284

Inspection Document #: 682404013

Larimer County, CO

NESW Section 7 T9N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: WELLINGTON MUDDY UNIT #25-1

API: 05-069-05284



Photo 1. Photo taken from the well location, facing North. List B Colorado noxious weeds (thistles) observed throughout the entire well location.



Photo 2. Photo illustrates Scotch thistle rosettes.

Inspection Photos

Location Name: WELLINGTON MUDDY UNIT #25-1

API: 05-069-05284



Photo 3. Photo taken from the well location. See comment under Photo 2.



Photo 4. Photo taken from the well location. See comment under Photo 2.