

# HALLIBURTON

iCem<sup>®</sup> Service

**EXTRACTION OIL & GAS-EBUS**

**VT LDS 3-16-18 Surface**

Sincerely,  
**Meghan Jacobs**

## Legal Notice

---

### Disclaimer:

All information in this report is provided subject to the terms and conditions which govern the services provided by Halliburton. Halliburton personnel use their best efforts in gathering information and their best judgment in interpreting it, but any interpretation, research, analysis or recommendation furnished by Halliburton are opinions based upon inferences from measurements and empirical relationships and assumptions, which inferences and empirical relationships and assumptions are not infallible, and with respect to which professionals in the industry may differ. iCem 3D Displacement results are used to understand how fluids intermix during a cement job. Simulation and 3D displacement results are not intended as and should not be used as a replacement for bond logs in determining top of cement. Current 3D model calculations are known to model more volume than the input volume for standard cases due to known calculation improvements required. For rotational cases, the modeled volume will be impacted by the same calculations impacting the standard cases, as well as additional constraints imposed to make the calculation time required operationally feasible. Therefore, until further notice, 3D displacement results should not be used for replacement of a bond log, or used as an identifier of top of cement. HALLIBURTON IS UNABLE TO GUARANTEE THE ACCURACY OF ANY CHART INTERPRETATION, RESEARCH ANALYSIS, OR JOB RECOMMENDATION and any interpretation or recommendation is not for use of or reliance upon by any third party. The customer has full responsibility for any of its decisions which are based on the information provided in this report.

## Table of Contents

---

1.0	Cementing Job Summary .....	4
1.1	Executive Summary .....	4
2.0	Real-Time Job Summary .....	7
2.1	Job Event Log .....	7
3.0	Attachments.....	9
3.1	VT LDS 3-16-18 Surface – Job Chart with Events.....	9
3.2	VT LDS 3-16-18 Surface – Job Chart without Events .....	10

## 1.0 Cementing Job Summary

---

### 1.1 Executive Summary

---

Halliburton appreciates the opportunity to perform the cementing services on the **VT LDS 3-16-18 cement Surface** casing job. A pre-job safety meeting was held before the job where details of the job were discussed, potential safety hazards were reviewed, and environmental compliance procedures were outlined.

**Approximately 56bbls of cement returned to surface.**

Halliburton maintains a continuous quality improvement process and appreciates any comments or suggestions that you may have. Halliburton again thanks you for the opportunity to perform service work on this well. We hope to be your solutions provider for future projects.

Respectfully,

**Halliburton [Ft. Lupton]**

**HALLIBURTON**

**Cementing Job Summary**

*The Road to Excellence Starts with Safety*

Sold To #: 369404	Ship To #: 3786957	Quote #:	Sales Order #: 0904877725
Customer: EXTRACTION OIL & GAS -		Customer Rep: Sean McIntyre	
Well Name: VT-LDS	Well #: 3-16-18	API/UWI #: 05-123-44417-00	
Field: WATTENBERG	City (SAP): GREELEY	County/Parish: WELD	State: COLORADO
Legal Description: SW NW-15-5N-65W-1892FNL-578FWL			
Contractor: Shawn McIntyre		Rig/Platform Name/Num: Cartel 11	
Job BOM: 7521 7521			
Well Type: HORIZONTAL OIL			
Sales Person: HALAMERICA\HX38199		Srvc Supervisor: Thomas Haas	
<b>Job</b>			

Formation Name			
Formation Depth (MD)	Top		Bottom
Form Type			BHST
Job depth MD	1601ft		Job Depth TVD 1601
Water Depth			Wk Ht Above Floor 4
Perforation Depth (MD)	From		To

Well Data										
Description	New / Used	Size in	ID in	Weight lbm/ft	Thread	Grade	Top MD ft	Bottom MD ft	Top TVD ft	Bottom TVD ft
Open Hole Section			13.5				0	1600	0	1600
Casing	0	9.625	8.921	36	8 RD	J-55	0	1601	0	1601

Tools and Accessories									
Type	Size in	Qty	Make	Depth ft		Type	Size in	Qty	Make
Guide Shoe	9.625					Top Plug	9.625	1	HES
Float Shoe	9.625			1601		Bottom Plug	9.625		
Float Collar	9.625			1559		SSR plug set	9.625		
Insert Float	9.625					Plug Container	9.625	1	HES
Stage Tool	9.625					Centralizers	9.625		

Fluid Data									
Stage/Plug #: 1									
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft <sup>3</sup> /sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
1	Red Dye Spacer	Red Dye Spacer	50	bbl	8.33				2100
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft <sup>3</sup> /sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
2	SwiftCem	SWIFTCEM (TM) SYSTEM	675	sack	13.5	1.74	9.2	5	6210
9.20 Gal		FRESH WATER							

**HALLIBURTON**

*Cementing Job Summary*

Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft <sup>3</sup> /sack	Mix Fluid Gal	Rate bbl/mi n	Total Mix Fluid Gal
3	Fresh Water	Fresh Water	121	bbl	8.33				5082
Cement Left In Pipe		Amount	42 ft		Reason			Shoe Joint	
Mix Water:		pH 7	Mix Water Chloride:		<300 ppm		Mix Water Temperature:		
Cement Temperature:		N/A	Plug Displaced by:		8.33 lb/gal F.W.		Disp. Temperature:		
Plug Bumped?		Yes	Bump Pressure:		450 psi		Floats Held?		
Cement Returns:		N/A	Returns Density:		N/A		Returns Temperature:		
Comment Pumped calculated displacement, plug bumped final circulating pressure of 450 PSI, held 5 min casing test. Released pressure back to truck, floats held 1 bbl back. 56 bbl cement back to surface.									

## 2.0 Real-Time Job Summary

### 2.1 Job Event Log


Type	Seq. No.	Activity	Graph Label	Date	Time	Source	DH Density <i>(ppg)</i>	Comb Pump Rate <i>(bbl/min)</i>	PS Pump Press <i>(psi)</i>	Comments
Event	1	Call Out	Call Out	5/25/2018	06:00:00	USER				CREW CALLED OUT AT 06:00 5/26/2018, REQUESTED ON LOCATION 12:00 5/26/2018. CREW PICKED UP CEMENT, 100 LBS SUGAR, AND PLUG CONTAINER FROM FORT LUPTON, CO. BULK 660: 12350112/10866484 Bulk 660: 12154546/10991603 PUMP RED TIGER: 11542778
Event	2	Pre-Convoy Safety Meeting	Pre-Convoy Safety Meeting	5/25/2018	10:15:00	USER				DISCUSSED ROUTES, HAZARDS, AND COMMUNICATION WITH CREW
Event	3	Crew Leave Yard	Crew Leave Yard	5/25/2018	10:30:00	USER				STARTED JOURNEY MANAGEMENT.
Event	4	Arrive At Loc	Arrive At Loc	5/25/2018	11:45:00	USER				END JOURNEY MANAGEMENT. MEET WITH CO. MAN TO DISCUSS JOB; SURFACE CASING: 36# 9.625" J-55 @ 1601', 42' SHOE JOINT, 13.5" OPEN HOLE, 9.0 PPG WELL FLUID, FRESH WATER DISPLACEMENT.
Event	5	Pre-Rig Up Safety Meeting	Pre-Rig Up Safety Meeting	5/26/2018	02:30:00	USER				HAZARD HUNT. DISCUSSED POSSIBLE HAZARDS ASSOCIATED WITH LOCATION, RIG UP AND WEATHER.
Event	6	Rig-Up Equipment	Rig-Up Equipment	5/26/2018	02:45:00	USER				CREW STAGED EQUIPMENT AND RIGGED UP BULK, IRON, AND WATER HOSES TO PERFORM JOB.
Event	7	Pre-Job Safety Meeting	Pre-Job Safety Meeting	5/26/2018	04:00:00	USER	8.55	0.00	5.00	MEETING WITH HALLIBURTON AND RIG PERSONNEL. COMMUNICATED POTENTIAL SAFETY HAZARDS AND JOB DETAILS.
Event	8	Start Job	Start Job	5/26/2018	05:12:30	COM4	8.40	0.00	1.00	START JOB DATA RECORDING.
Event	9	Test Lines	Test Lines	5/26/2018	05:16:50	COM4	8.40	0.00	18.00	PRESSURE TESTED IRON TO 3150 PSI. KICKOUTS SET @ 500 PSI, KICKED OUT @ 800 PSI, 5TH GEAR STALL OUT @1880 PSI.
Event	10	Pump Spacer 1	Pump Spacer 1	5/26/2018	05:22:45	COM4	8.40	0.00	7.00	PUMP 40 BBL FRESH WATER SPACER.
Event	11	Pump Spacer 2	Pump Spacer 2	5/26/2018	05:34:06	COM4	8.40	3.40	73.00	PUMP 10 BBL RED DYE FRESH WATER SPACER.
Event	12	Pump Cement	Pump Cement	5/26/2018	05:37:42	COM4	13.39	3.40	87.00	PUMP 675 SKS OF SWIFTCEM @ 13.5 LB/GAL, 1.74

YIELD, 9.2 GAL/SK, 209 BBLs, TOL @ SURFACE, DENSITY VERIFIED BY PRESSURIZED MUD SCALES.


Event	13	Shutdown	Shutdown	5/26/2018	06:23:35	COM4	0.27	0.00	17.00	SHUTDOWN TO DROP TOP PLUG.
Event	14	Drop Top Plug	Drop Top Plug	5/26/2018	06:23:40	COM4	0.27	0.00	16.00	PLUG LEFT CONTAINER.
Event	15	Pump Displacement	Pump Displacement	5/26/2018	06:23:44	COM4	0.27	0.00	16.00	BEGIN CALCULATED DISPLACEMENT OF 121 BBL.
Event	16	Other	Cement Returned To Surface	5/26/2018	06:40:04	COM4	8.38	6.10	366.00	CEMENT RETURNED TO SURFACE 65 BBL INTO DISPLACEMENT. 56 TOTAL BBL RETURNED TO SURFACE.
Event	17	Bump Plug	Bump Plug	5/26/2018	06:54:41	COM4	8.40	2.10	563.00	PLUG BUMPED AT CALCULATED DISPLACEMENT. PRESSURED 500 PSI OVER FINAL CIRCULATING PRESSURE OF 405 PSI.
Event	18	Shutdown	Pressure Test	5/26/2018	06:55:03	COM4	8.40	0.00	1190.00	SHUTDOWN FOR A 5 MIN. PRESSURE TEST.
Event	19	Check Floats	Check Floats	5/26/2018	07:00:00	USER	8.40	0.00	1233.00	RELEASE PRESSURE 1 BBL BACK TO TRUCK.
Event	20	End Job	End Job	5/26/2018	07:01:40	COM4	8.40	0.00	9.00	
Event	21	Pre-Rig Down Safety Meeting	Pre-Rig Down Safety Meeting	5/26/2018	07:10:00	USER	6.56	0.00	4.00	DISCUSSED POSSIBLE HAZARDS ASSOCIATED WITH WEATHER, LOCATION AND RIGGING DOWN IRON AND HOSES.
Event	22	Rig-Down Completed	Rig-Down Completed	5/26/2018	07:40:00	USER				ALL HALLIBURTON ITEMS WERE STOWED FOR TRAVEL.
Event	23	Pre-Convoy Safety Meeting	Pre-Convoy Safety Meeting	5/26/2018	07:45:00	USER				DISCUSSED ROUTES HAZARDS AND COMMUNICATION WITH CREW.
Event	24	Crew Leave Location	Crew Leave Location	5/26/2018	08:00:00	USER				THANK YOU FOR USING HALLIBURTON - THOMAS HAAS AND CREW.

3.0 Attachments

3.1 VT LDS 3-16-18 Surface – Job Chart with Events



3.2 VT LDS 3-16-18 Surface – Job Chart without Events



HALLIBURTON | iCem® Service

Created: 2018-05-26 03:19:51, (UTC-06:00), Version: 4.5.139

Edit

Customer: EXTRACTION OIL & GAS  
 Representative: Thomas Haas

Job Date: 5/26/2018  
 Sales Order #: 904877725

Well: VT LDS  
 Red Tiger Operator: 11542778:Matt Smith