

Inspection Photos

10/02/2018

Operator: BISON OIL & GAS II LLC - 10661

Location ID: 455627

Inspection Doc. Number: 682503958

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the access road entrance at CR 96. Initial construction activities observed include road construction. Operator has installed cattle guard to act as a tracking pad. Contractor on site indicated and additional tracking pad will be installed between cattle guard and CR



10.02.2018

Photo 2: Photo taken from the west end of the staked wells on location, facing northeast. Construction activities on pad have not yet begun. Photo shows vegetation on location pre-disturbance.



Photo 3: Photo taken from the staked wells on location. Photo shows topsoil depth at the center of the location appears to be at least 6 inches in depth. Operator will need to determine topsoil depths at other areas of the location to ensure sufficient topsoil salvage will be conducted in accordance with 1002.b(2)