

# Inspection Photos

10/02/2018

Operator: NOBLE ENERGY INC - 100322

Location ID: 425138

Inspection Doc. Number: 682503962

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 425138



**Photo 1:** Photo of PR well.



**Photo 2:** Photo taken from the northwest interim area of the location, facing south. Photo shows vegetation within the interim appears to be progressing towards reclamation standards.





**Photo 3:** Photo taken from the northwest interim area of the location, facing east. Photo shows vegetation within the interim appears to be progressing towards reclamation standards.





**Photo 4:** Photo taken from the interim areas. Photo shows vegetation within the interim appears to be progressing towards reclamation standards.





**Photo 5:** Photo of tank battery. 6 total 300 bbl AST; 5 crude, 1 produced water.



**Photo 6:** Photo of equipment on site.





**Photo 7:** Photo of equipment on site.





**Photo 8:** Photo of equipment on site.