

Inspection Photos

10/02/2018

Operator: NOBLE ENERGY INC - 100322

Location ID: 431817

Inspection Doc. Number: 682503967

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the east end of the two PR wells on location, facing west. Photo shows well API 123-36799 in foreground, and well 123-36800 in background. Photo also shows that the AL well 123-36831 does not appear to have been drilled.



Photo 2: Photo taken from the PR wells, facing southwest. Photo shows that the AL well 123-36831 does not appear to have been drilled.