

Final Reclamation Inspection

September 27, 2018

Operator: MAGPIE OPERATING, INC- # 52530

API: 05-069-06112

Inspection Document #: 682404028

Larimer County, CO

SESE Section 29 T5N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SAULCY #3
API: 05-069-06112



Photo 1. Photo taken from a portion of the northern disturbance area, facing South. Crop growth is not reflective of reference area levels and even absent in some areas.



Photo 2. Photo taken from the entrance of the well location access road, facing North. See comments under Photo 1.