

Inspection Photos

API#081-07015

Operator: Wexpro

Inspection Number: 692400182

Inspection Date: 9/26/2018





Photo#1:
Overview of Location to Northwest.

September 26 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Wexpro Chapman State API#081-07015



Photo#2:

View to South over Location; position of spill area shown in following photo circled in Red.

September 26 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Wexpro Chapman State API#081-07015



Photo#3:


Pooling of what appears to be Oil at at area where equipment & piping are being dismanteled.

September 26 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Wexpro Chapman State API#081-07015



Photo#4:
Location appears to be in Process of Abandonment

September 26 2018



Photo#5: