

Inspection Photos

Location Name: Lind #1, 9, 10, 15, 16, 24-6 production facility

Location ID 333159



Photo 1 – Location Sign



Photo 2 – Erosion; sediment transported off east side of site



Inspection Photos

Location Name: Lind #1, 9, 10, 15, 16, 24-6 production facility

Location ID 333159



Photo 3 – Erosion; sediment transported off east side of site



Photo 4– Erosion; sediment transported off east side of site



Inspection Photos

Location Name: Lind #1, 9, 10, 15, 16, 24-6 production facility

Location ID 333159



Photo 5 - Site Photo



Photo 6 – Site Photo



Inspection Photos

Location Name: Lind #1, 9, 10, 15, 16, 24-6 production facility

Location ID 333159



Photo 7 - Site Photo



Photo 8 – Site Photo



Inspection Photos

Location Name: Lind #1, 9, 10, 15, 16, 24-6 production facility

Location ID 333159



Photo 9 - Site Photo



Photo 10 – Monitoring wells; REM 10535

