

Inspection Photos
Location Name: Aristocrat Angus 1-4
Location ID 422974



Photo 1 – Location Sign



Photo 2 – Erosion; sediment transported off west side of site

Inspection Photos
Location Name: Aristocrat Angus 1-4
Location ID 422974



Photo 3 – Erosion; sediment transported off west side of site



Photo 4– Erosion; sediment transported off west side of site

Inspection Photos
Location Name: Aristocrat Angus 1-4
Location ID 422974



Photo 5 - Site Photo



Photo 6 – Site Photo

Inspection Photos
Location Name: Aristocrat Angus 1-4
Location ID 422974



Photo 7 - Site Photo



Photo 8 – Site Photo