

Inspection Photos

Location Name: Lucci B - 65N64W / 1NWSW

Location #: 302891



Colorado Oil & Gas Conservation Commission
40.42483, -104.5033, 1384.0m, 86°
2018/10/03 12:15:22 PM

Photo #1

Lucci B 1-25 (API # 05-123-29983) wellsite



Colorado Oil & Gas Conservation Commission
40.4234, -104.50096, 1387.0m, 209°
2018/10/03 01:09:55 PM

Photo #2

Lucci B 1-25, 1-24
Lucci BC B 1-11, 1-12
Battery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Lucci B - 65N64W / 1NWSW

Location #: 302891



Photo #3

Lucci B 1-25, 1-24

Lucci BC B 1-11, 1-12

Crude oil tanks – Contents | Capacity – Not legible



Photo #4

Lucci B 1-25, 1-24

Lucci BC B 1-11, 1-12

Produced H2O vaults – Capacity – Not legible

Inspection Photos

Location Name: Lucci B - 65N64W / 1NWSW

Location #: 302891



Photo #5

Lucci B 1-25, 1-24

Lucci BC B 1-11, 1-12

Gas mtr house – Unused Equipment

From prev. FIR



Photo #6

Lucci B 1-25, 1-24

Lucci BC B 1-11, 1-12

Gas mtr house – Removed from location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources