

Inspection Photos
Location Name: Walker 3-1
API: 05-081-07050



Photo 1. Overview of location taken at entrance facing southwest.

Inspection Photos
Location Name: Walker 3-1
API: 05-081-07050



Photo 2. Unmarked riser.




Photo 2. Unmarked risers.