

Inspection Photos
Location Name: Walker 3-3
API: 05-081-07099



Photo 1. Overview of location taken at entrance facing northeast.

Inspection Photos
Location Name: Walker 3-3
API: 05-081-07099



Photo 2. Unmarked risers.



Photo 3. Unmarked risers.