

Inspection Photos
Location Name: Walker 2-11
API: 05-081-07161



Photo 1. Overview of location taken at entrance facing east.

Inspection Photos
Location Name: Walker 2-11
API: 05-081-07161



Photo 2. Unmarked risers.



Photo 3. Unmarked risers.