

Inspection Photos
Location Name: Walker 2-12
API: 05-081-07160



Photo 1. Overview of location taken at entrance facing south.

Inspection Photos
Location Name: Walker 2-12
API: 05-081-07160



Photo 2. Unmarked risers.



Photo 3. Unmarked risers.