

Inspection Photo
Clough RWF 414-14
API # 045-13598
Inspection # 689302054



Location Photo #1



Location Photo #2

Inspection Photo
Clough RWF 414-14
API # 045-13598
Inspection # 689302054



Location Photo #3 Wellhead sign not legible from a short distance.



Location Photo #4, uncontrolled weeds by wellhead.

**Inspection Photo
Clough RWF 414-14
API # 045-13598
Inspection # 689302054**



Location Photo #5, uncontrolled weeds on location.



Location Photo #6, uncontrolled weeds near separators.

Inspection Photo
Clough RWF 414-14
API # 045-13598
Inspection # 689302054



Location Photo #7, uncontrolled weeds near tank battery.

