

Inspection Photos
Location Name: Simson 9
Location ID: 319940



Colorado Oil and Gas Conservation Commission
39.99508, -103.83287, 1485.6m
Oct 4, 2018 08:31:12

Photo 1 WH



Colorado Oil and Gas Conservation Commission
39.99499, -103.83231, 1453.2m
Oct 4, 2018 08:32:28

Photo 2 TNK BTRY

Inspection Photos
Location Name: Simson 9
Location ID: 319940



Photo 3 Loc Pic



Photo 4 Unused equipment

Inspection Photos
Location Name: Simson 9
Location ID: 319940



Photo 5 Sep pic



Photo 6 Unused sucker rods

Inspection Photos
Location Name: Simson 9
Location ID: 319940



Photo 7 No signs or labels



Photo 8 Stained soil behind crude oil tanks

Inspection Photos
Location Name: Simson 9
Location ID: 319940



Photo 9 Pit pic, Unused 3" Pipe on birm