

Final Reclamation Inspection

October 4, 2018

Operator: NOBLE ENERGY INC- #100322

API: 05-123-25222

Inspection Document #: 682404050

Weld County, CO

SWNE Section 36 T7N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: WADSWORTH #36-13
API: 05-123-25222



Photo 1. Photo taken from the well location, facing West. List B Colorado Noxious weeds, Canada thistle and Musk thistle, were observed at the well location. Also, subsidence was observed.



Photo 2. Photo illustrates Canada thistle and Musk thistle rosettes at the well location.

Inspection Photos
Location Name: WADSWORTH #36-13
API: 05-123-25222



Photo 3. Photo taken from the well location, facing North. Access road will remain IN-PROCESS as vegetative standards are not reflective of reference area levels.



Photo 4. Photo taken from a portion of the access road, facing West. See comments under Photo 3.

Inspection Photos
Location Name: WADSWORTH #36-13
API: 05-123-25222



Photo 5. Photo taken from a portion of the access road, facing East. See comments under Photo 3.



Photo 6. Reference photo taken west of the location, facing West.