

Inspection Photos

10/04/2018

Operator: WESTERN OPERATING COMPANY #
95620

Location ID: 312291

Inspection Doc. Number: 682503989

Logan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the east end of the well, facing southeast. Photo shows areas of the interim that operator previously regraded and seeded. Operator failed to implement required stabilization or stormwater and erosion control BMPs per CAs. Photo shows erosion degradation has been allowed to continue.



Photo 2: Photo taken from the east of the location, facing southeast. See comments under photo 1. 6 foot measuring stick for reference.



Photo 3: Photo taken from the southwest of the location, facing west. See comments under photo 1.



Photo 4: Photo taken from the southwest of the location, facing east. See comments under photo 1. 6 foot measuring stick for reference.



Photo 5: Photo taken from the west end of the location. Photo shows area where operator once repaired gully erosion, however no stabilization or stormwater and erosion controls were implemented. Erosion degradation has been allowed to continue.

Inspection Photos
Operator: WESTERN OPERATING COMPANY # 95620
Location ID: 312291



Photo 6: Photo taken from the west end of the location, facing east. See comments under photo 5.

Inspection Photos
Operator: WESTERN OPERATING COMPANY # 95620
Location ID: 312291



Photo 7: Photo taken from the center of the location, facing north. Photo shows barrel observed in previous inspection has been removed.