

# Inspection Photos

10/04/2018

Operator: WINSLOW RESOURCES INC - 97065

Location ID: 390108

Inspection Doc. Number: 682503991

Logan County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the southeast end of the location, facing northeast. Previous inspections documented that areas of the east end of the location and access road have not achieved a uniform desirable perennial vegetative cover, and stormwater has caused erosion degradation. Inspections required operator to perform reclamation and stormwater management. Photo shows no management activities per the CAs appear to have been conducted; location/access road has not been adequately contoured/graded and revegetated, sotrmwater has continued to cause erosion degradation.

Inspection Photos  
Operator: WINSLOW RESOURCES INC - 97065  
Location ID: 390108



**Photo 2:** See comments under photo 1.



**Photo 3:** Photo taken from the east end of the location, facing east. Photo shows gully erosion.

Inspection Photos  
Operator: WINSLOW RESOURCES INC - 97065  
Location ID: 390108



**Photo 4:** Photo taken from the northeast corner of the location, facing north. See comments under photo 1.



**Photo 5:** Photo taken from the east end of the location, facing northeast. Photo shows gully erosion. Photo also shows access road has not been recontoured/regraded to that of the adjacent lands, and stormwater has continued to degrade and channelize the access road creating a gully. 6 foot measuring stick for reference.



**Photo 6:** Photo taken from the east end of the location, facing southeast. Photo of access road. See comments under photo 5.



**Photo 7:** Photo taken from the east end of the location, facing northeast. Photo of access road. See comments under photo 5.



**Photo 8:** Photo taken from access road, facing northeast See comments under photo 5.



**Photo 9:** Photo taken from access road, facing northeast See comments under photo 5.



**Photo 10:** Photo taken from access road, facing northeast See comments under photo 5. 6 foot measuring stick for reference.

Inspection Photos  
Operator: WINSLOW RESOURCES INC - 97065  
Location ID: 390108



**Photo 11:** Photo taken from access road, facing southwest towards the location. See comments under photo 5.