

# *Inspection Photos*

*API#081-07013*

*Operator: Wexpro*

*Inspection Number: 692400200*

*Inspection Date: 9/26/2018*





Photo#1:  
Overview of Location to Northeast. Insert is of Debris noted on site.

September 26 2018



Photo#2:

View of area where straw mulch has remained crimped in and Russian thistle. Insert is close up of ground conditions where mulch has blown off.

September 26 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Wexpro PA Chapman State API#081-07013