

Inspection Photos

API#081-07244

Operator: Wexpro

Inspection Number: 692400202

Inspection Date: 9/26/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Overview of Location to East. Reclamation activities appear to be in process

September 26 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Wexpro PA State API#081-07244



Photo#2:

Some facilities (risers /lines) remain on site, though this work looks to be ongoing.

September 26 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Wexpro PA State API#081-07244