

**Inspection Photo**  
**Hilltop 2F2 Ranch RMV 109-4**  
**API # 045-13830**  
**Inspection # 689302076**



**Location Photo #1**



**Location Photo #2**

**Inspection Photo**  
**Hilltop 2F2 Ranch RMV 109-4**  
**API # 045-13830**  
**Inspection # 689302076**



**Location Photo #3**



**Location Photo #4, hole in secondary  
containment liner**



**Inspection Photo**  
**Hilltop 2F2 Ranch RMV 109-4**  
**API # 045-13830**  
**Inspection # 689302076**



**Location Photo #5, unused equipment**



**Location Photo #6, unused equipment**



**Inspection Photo**  
**Hilltop 2F2 Ranch RMV 109-4**  
**API # 045-13830**  
**Inspection # 689302076**



**Location Photo #7, Sediment movement onto location**



**Location Photo #8, Sediment movement onto location.**