

Inspection Photos

API#081-06940

Operator: Mull Drilling

Inspection Number: 692400212

Inspection Date: 9/27/2018





Photo#1:
Overview of Location from entry to North.

September 27, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Mull Drilling PA State Avalanche API#081-06940



Photo#2:

The entire location including the well pad & access road, are not re-contoured, de-compacted, or revegetated..

September 27, 2018

Photo#3:



Photo#4:
Views of un-reclaimed Access road.

September 27, 2018



Photo#5: