

Inspection Photos

API#081-06984

Operator: Samson Resources

Inspection Number: 692400227

Inspection Date: 9/27/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Overview of Location to Northwest. Vegetation is sparse & infested with annual weeds.

September 27, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Samson Res PA Evans API#081-06984



Photo#2:

Overview of Location to West. Vegetation is sparse & infested with annual weeds.

September 27, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Samson Res PA Evans API#081-06984



Photo#3:

Vegetation is sparse & infested with annual weeds. Soils appear hard packed & cracking.

September 27, 2018

Photo#4:



Photo#5:
View North over Location Center



Photo#6:
View South over Location Center

September 27, 2018



Photo#7:
View East over Location Center



Photo#8:
View West over Location Center

September 27, 2018