

Inspection Photos
Location Name: Wailes #2
Location ID: 320125



Photo 1 WH



Photo 2 rags and duck tape around packing and polish rod