

Inspection Photos
Location Name: Wailes #3
Location ID: 320157



Photo 1 WH



Photo 2 rags and tape around polish rod and packing

Inspection Photos
Location Name: Wailes #3
Location ID: 320157



Colorado Oil and Gas Conservation Commission
39.90239, -104.44865, 1555.3m
Oct 10, 2018 08:52:48

Photo 3 Unused belt guard