

Inspection Photos
Location Name: Chris Wailes
Location ID: 319820



Photo 1 WH



Photo 2 rags and electric tape around Plunger lift and WH

Inspection Photos
Location Name: Chris Wailes
Location ID: 319820



Photo 3 TNK BTRY



Photo 4 Sales line Locked out tagged out

Inspection Photos
Location Name: Chris Wailes #1
Location ID: 319820



Photo 5 Gas meter run all vlv's locked out tagged out