

# Final Reclamation Inspection

October 10, 2018

Operator: PDC ENERGY INC - 69175

API: 05-123-14566

Inspection Document #: 682404058

Weld County, CO

NENW Section 9 T5N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: ANNIE #3-9  
API: 05-123-14566



**Photo 1.** Photo taken from the location, facing West. Does not appear Final reclamation activities were performed per Rule 1004 and weedy, annual vegetation (Russian thistle and Kochia) has not been managed and controlled. Note: Operator did indicate a Final Reclamation variance was in process for a land use change (gravel mining); however, COGCC Staff will not consider a variance until the Operator controls and manages weeds.

Inspection Photos  
Location Name: ANNIE #3-9  
API: 05-123-14566



**Photo 2.** Photo taken from the location, facing North. See comments under Photo 1.



Inspection Photos  
Location Name: ANNIE #3-9  
API: 05-123-14566



**Photo 3.** Photo taken from the location, facing East. See comments under Photo 1.

Inspection Photos  
Location Name: ANNIE #3-9  
API: 05-123-14566



**Photo 4.** Photo taken from the location, facing South. See comments under Photo 1.