

# Construction and Stormwater Inspection

October 10, 2018

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 443166

Inspection Document #: 682404060

Weld County, CO

NENW Section 9 T5N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: ASH /9-B  
Location ID: 443166



**Photo 1.** Photo taken from the entrance of location off, facing West. Access road appears to be in good condition. Note: Truck traffic was observed due to a nearby PDC remediation project.



**Photo 2.** Photo taken from the western perimeter of the location, facing South. Silt fence BMP has been installed around the perimeter of the location.

Inspection Photos  
Location Name: ASH /9-B  
Location ID: 443166



**Photo 3.** Photo taken from the southwestern perimeter of the location, facing North. Photo illustrates the topsoil stockpile stored along the southwestern perimeter of the location. Topsoil has been temporarily stabilized with equipment tracking.



**Photo 4.** Photo taken from the southern perimeter of the location, facing South. Photo illustrates a portion of the silt fence that has not been properly trenched.

Inspection Photos  
Location Name: ASH /9-B  
Location ID: 443166



**Photo 5.** Photo taken from the eastern perimeter of the location, facing North. See comments under Photo 2.



**Photo 6.** Photo taken from the northwestern perimeter of the location, facing South. See comments under Photo 2.