

Inspection Photos

Operator: BP Production

API: 05-067-06338

Date: 10/03/2018



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Vegetation is becoming established with grasses such as western wheatgrass (*Pascopyrum smithii*) and forbs such as snakeweed (*Gutierrezia sarothrae*).



Photo 2. View of the western project area from the southwestern corner facing northward.