

**Inspection Photo**  
**Shideler 33-4D**  
**API # 045-09408**  
**Inspection # 689302101**



**Location Photo #1**



**Location Photo #2**

**Inspection Photo**  
**Shideler 33-4D**  
**API # 045-09408**  
**Inspection # 689302101**



**Location Photo #3**



**Location Photo #4, unused equipment**



**Inspection Photo**  
**Shideler 33-4D**  
**API # 045-09408**  
**Inspection # 689302101**



**Location Photo #5, Stained rock in battery  
containment.**