

**Inspection Photo**  
**Bennett 33-5**  
**API # 045-07254**  
**Inspection # 689302103**



**Location Photo #1**



**Location Photo #2**

**Inspection Photo  
Bennett 33-5  
API # 045-07254  
Inspection # 689302103**



**Location Photo #3**



**Location Photo #4, Unused equipment, East of Wellheads**



**Inspection Photo  
Bennett 33-5  
API # 045-07254  
Inspection # 689302103**



**Location Photo #5, unmarked deadman**



**Location Photo #6, hole in berm, south corner of separators.**