

**Inspection Photo**  
**Boulton 33-6A**  
**API # 045-07927**  
**Inspection # 689302105**



**Location Photo #1**



**Location Photo #2**

**Inspection Photo**  
**Boulton 33-6A**  
**API # 045-07927**  
**Inspection # 689302105**



0/11/18

**Location Photo #3**



0/11/18

**Location Photo #4, unused equipment**



**Inspection Photo**  
**Boulton 33-6A**  
**API # 045-07927**  
**Inspection # 689302105**



**Location Photo #5, unused equipment**



**Location Photo #6, unused equipment**



**Inspection Photo**  
**Boulton 33-6A**  
**API # 045-07927**  
**Inspection # 689302105**



**Location Photo #7, unused equipment**



**Location Photo #8, unmarked deadman.**



**Inspection Photo**  
**Boulton 33-6A**  
**API # 045-07927**  
**Inspection # 689302105**



**Location Photo #9, stained rock in battery containment.**



**Location Photo #10, stained rock in battery containment**



**Inspection Photo**  
**Boulton 33-6A**  
**API # 045-07927**  
**Inspection # 689302105**



**Location Photo #11, storm water issue North side of location, near separator**



**Location Photo #12, Storm water issue.**

**Inspection Photo**  
**Boulton 33-6A**  
**API # 045-07927**  
**Inspection # 689302105**



**Location Photo #13, storm water issue,  
sediment being moved off location.**