

Inspection Photos
Location Name: Lewton Company F Unit 1
Location ID: 320303



Colorado Oil and Gas Conservation Commission
39.92298, -104.37365, 1544.2m
Oct 11, 2018 11:56:36



Colorado Oil and Gas Conservation Commission
39.92296, -104.37453, 1544.5m
Oct 11, 2018 12:01:58

Photo 1 Well Head Weeds

Photo 2 TNK BTRY Berm cannot hold volume of tank's

Inspection Photos
Location Name: Lewton Company F Unit 1
Location ID: 320303



Photo 3 Sep

Photo 4 Meter house locked out tagged out

Inspection Photos
Location Name: Lewton Company F Unit 1
Location ID: 320303



Photo 35 Produced water tank no signage