

Inspection Photos
Location Name: Handke #4
Location ID: 428424



Photo 1 stained soil between crude oil tanks