

Inspected Facilities

Facility ID: 239560 Type: WELL API Number: 123-07347 Status: SI Insp. Status: SI

COGCC Comments

Comment	User	Date
<p>This inspection is based on FIR resolution 401740034. There was no need to visit location as corrective action was regarding documents therefore there are no location photos. This is a follow up inspection to DOC. ID 691401178. All corrective actions have been completed. Any corrective actions from previous inspections that have not been address are still applicable.</p>	beardsit	10/12/2018