

Inspected Facilities

Facility ID: 243117 Type: WELL API Number: 123-10908 Status: TA Insp. Status: TA

COGCC Comments

Comment	User	Date
This is a follow up inspection to DOC. ID 691400436. All corrective actions have been completed. MIT DOC#401726132	beardsit	10/12/2018