

Location Name: H&M Petroleum Corp. (Catherine #3 075-09334)

Inspection Date: 8/13/2018



Photo # - 1



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: H&M Petroleum Corp. (Catherine #3 075-09334)

Inspection Date: 8/13/2018



Photo # - 2

View south along access road from the tank battery



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: H&M Petroleum Corp. (Catherine #3 075-09334)

Inspection Date: 8/13/2018



Photo # - 3

View west at the tank battery



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: H&M Petroleum Corp. (Catherine #3 075-09334)

Inspection Date: 8/13/2018



Photo # - 4

View east at TA well



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: H&M Petroleum Corp. (Catherine #3 075-09334)

Inspection Date: 8/13/2018



Photo # - 5

View north from southeast corner of tank battery, uncontrolled weeds



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: H&M Petroleum Corp. (Catherine #3 075-09334)

Inspection Date: 8/13/2018



Photo # - 6

Uncontrolled weeds inside tank battery berm



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: H&M Petroleum Corp. (Catherine #3 075-09334)

Inspection Date: 8/13/2018



Photo # - 7

Uncontrolled weeds inside separator berm



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: H&M Petroleum Corp. (Catherine #3 075-09334)

Inspection Date: 8/13/2018



Photo # - 8

Uncontrolled weeds around tank battery



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: H&M Petroleum Corp. (Catherine #3 075-09334)

Inspection Date: 8/13/2018



Photo # - 9

View west at oil skim tank and production pits, uncontrolled weeds



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: H&M Petroleum Corp. (Catherine #3 075-09334)

Inspection Date: 8/13/2018



Photo # - 10

View south along inside production pit east berm areas of oil accumulation



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: H&M Petroleum Corp. (Catherine #3 075-09334)

Inspection Date: 8/13/2018



Photo # - 11

View east along inside production pit north berm areas of oil accumulation



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: H&M Petroleum Corp. (Catherine #3 075-09334)

Inspection Date: 8/13/2018




Photo # - 12

View southeast inside production pit at areas of oil accumulation



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: H&M Petroleum Corp. (Catherine #3 075-09334)

Inspection Date: 8/13/2018



Photo # - 13

Closeup view of oil accumulation in the southwest corner of the production pit



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: H&M Petroleum Corp. (Catherine #3 075-09334)

Inspection Date: 8/13/2018



Photo # - 14

View of oil accumulation in the southwest corner of the production pit



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: H&M Petroleum Corp. (Catherine #3 075-09334)

Inspection Date: 8/13/2018



Photo # - 15

View north of oil accumulation on the inside of the north berm of the production pit



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: H&M Petroleum Corp. (Catherine #3 075-09334)

Inspection Date: 8/13/2018



Photo # - 16

View east of oil accumulation on the inside of the southeast corner of the production pit



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Location Name: H&M Petroleum Corp. (Catherine #3 075-09334)

Inspection Date: 8/13/2018



Photo # - 17

View northeast at oil skim tank surrounded by weeds and overgrown vegetation



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources