



PHOTO: VIEW OF AS-DRILLED LOCATION

CAMERA ANGLE: NORTHERLY




PHOTO: VIEW OF AS-DRILLED LOCATION

CAMERA ANGLE: EASTERLY

REV: 1 10-08-18 C.IVIE (ADD FOOTAGES)

BISON OIL & GAS II

BUTLER 1
1978' FSL 1980' FEL
NW 1/4 SE 1/4, SECTION 17, T8N, R60W, 6th P.M.
WELD COUNTY, COLORADO

TAKEN BY	J.F.	08-28-18	
DRAWN BY	C.IVIE	09-04-18	
LOCATION PHOTOS			PHOTO 1



UELS, LLC
 Corporate Office * 85 South 200 East
 Vernal, UT 84078 * (435) 789-1017




PHOTO: VIEW OF AS-DRILLED LOCATION

CAMERA ANGLE: SOUTHERLY



PHOTO: VIEW OF AS-DRILLED LOCATION

CAMERA ANGLE: WESTERLY

REV: 1 10-08-18 C.IVIE (ADD FOOTAGES)

BISON OIL & GAS II

BUTLER 1
1978' FSL 1980' FEL
NW 1/4 SE 1/4, SECTION 17, T8N, R60W, 6th P.M.
WELD COUNTY, COLORADO

TAKEN BY	J.F.	08-28-18	
DRAWN BY	C.IVIE	09-04-18	
LOCATION PHOTOS			PHOTO 2



UELS, LLC
 Corporate Office * 85 South 200 East
 Vernal, UT 84078 * (435) 789-1017