



PHOTO: VIEW OF DRILLED AND ABANDONED LOCATION

CAMERA ANGLE: NORTHERLY



PHOTO: VIEW OF DRILLED AND ABANDONED LOCATION

CAMERA ANGLE: EASTERLY

BISON OIL & GAS II

H H DUELL 1
336' FSL 2306' FWL
SE 1/4 SW 1/4, SECTION 1, T8N, R61W, 6th P.M.
WELD COUNTY, COLORADO

TAKEN BY	G.W., J.F.	10-13-17	
DRAWN BY	D.COX	10-18-17	
LOCATION PHOTOS			PHOTO 1



UELS, LLC
 Corporate Office * 85 South 200 East
 Vernal, UT 84078 * (435) 789-1017



PHOTO: VIEW OF DRILLED AND ABANDONED LOCATION

CAMERA ANGLE: SOUTHERLY



PHOTO: VIEW OF DRILLED AND ABANDONED LOCATION

CAMERA ANGLE: WESTERLY

BISON OIL & GAS II

H H DUELL 1
336' FSL 2306' FWL
SE 1/4 SW 1/4, SECTION 1, T8N, R61W, 6th P.M.
WELD COUNTY, COLORADO

TAKEN BY	G.W., J.F.	10-13-17	
DRAWN BY	D.COX	10-18-17	
LOCATION PHOTOS			PHOTO 2



UELS, LLC
 Corporate Office * 85 South 200 East
 Vernal, UT 84078 * (435) 789-1017