

**Inspection Photo**  
**Downing RWF 522-24**  
**API # 045-17901**  
**Inspection # 689302114**



**Location Photo #1**



**Location Photo #2**

**Inspection Photo**  
**Downing RWF 522-24**  
**API # 045-17901**  
**Inspection # 689302114**



**Location Photo #3, unused equipment.**



**Location Photo #4, unused equipment.**



**Inspection Photo**  
**Downing RWF 522-24**  
**API # 045-17901**  
**Inspection # 689302114**



**Location Photo #5, rutted access road**



**Location Photo #6, rutted access road**