

**Inspection Photo
Mead RWF 342-23
API # 045-20040
Inspection # 689302118**



Location Photo #1



Location Photo #2

**Inspection Photo
Mead RWF 342-23
API # 045-20040
Inspection # 689302118**



Location Photo #3



Location Photo #4, Unused equipment

**Inspection Photo
Mead RWF 342-23
API # 045-20040
Inspection # 689302118**



Location Photo #5, debris on location



Location Photo #6, unmarked unused flow lines.

**Inspection Photo
Mead RWF 342-23
API # 045-20040
Inspection # 689302118**



**Location Photo #7, Uncontrolled
weeds/debris on location**



**Location Photo #8, Uncontrolled
weeds/debris on location**

**Inspection Photo
Mead RWF 342-23
API # 045-20040
Inspection # 689302118**



**Location Photo #9, Uncontrolled
weeds/debris on location**



**Location Photo #10, Uncontrolled
weeds/debris on location**