


Inspection Photo
Mead 23-44-6S-94W
API # 045-06556
Inspection # 689302120



Location Photo #1



Location Photo #2, missing wellhead sign information.

Inspection Photo
Mead 23-44-6S-94W
API # 045-06556
Inspection # 689302120



Location Photo #3, missing tank information



Location Photo #4, uncontrolled weeds on location.

Inspection Photo
Mead 23-44-6S-94W
API # 045-06556
Inspection # 689302120



Location Photo #5, uncontrolled weeds on location.



Location Photo #6, uncontrolled weeds on location.

Inspection Photo
Mead 23-44-6S-94W
API # 045-06556
Inspection # 689302120



Location Photo #7, uncontrolled weeds on location.



Location Photo #8, Mechanical condition.