

Inspection Photos

10/12/2018

Operator: NOBLE ENERGY INC - 100322

Location ID: 329000

Inspection Doc. Number: 682504014

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 329000



Photo 1: Photo from the location, facing north. Photo shows vegetation over the reclamation area. Location is bare and exposed soil or predominantly undesirable weedy plant species such as Russian Thistle.



Photo 2: Photo from the location, facing east. Photo shows vegetation over the reclamation area. Location is bare and exposed soil or predominantly undesirable weedy plant species such as Russian Thistle.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 329000



Photo 3: Photo from the location, facing south. Photo shows vegetation over the reclamation area. Location is bare and exposed soil or predominantly undesirable weedy plant species such as Russian Thistle.



Photo 4: Photo from the location, facing west. Photo shows vegetation over the reclamation area. Location is bare and exposed soil or predominantly undesirable weedy plant species such as Russian Thistle.



Photo 5: Photo taken from the well location. Photo shows vegetation on location. Location is bare and exposed soil or predominantly undesirable weedy plant species such as Russian Thistle.



Photo 6: Photo taken from the adjacent reference area of the well. Photo shows vegetation is predominantly perennial saltgrass.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 329000



Photo 7: Photo taken from the southeast corner of the battery location, facing northwest. Photo shows fence remains and location has not been reclaimed.



Photo 8: Photo taken from the southeast corner of the battery location, facing north. Photo shows fence remains and location has not been reclaimed.