

Inspection Photos

10/12/2018

Operator: NOBLE ENERGY INC - 100322

Location ID: 327240

Inspection Doc. Number: 682504020

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 327240



Photo 1: Photo taken from the battery location, facing west. Photo shows riser has been removed.



Photo 2: Photo taken from the battery location, facing east. Photo shows riser has been removed.