

Inspection Photos

10/12/2018

Operator: NOBLE ENERGY INC - 100322

Location ID: 327399

Inspection Doc. Number: 682504026

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 327399



Photo 1: Photo taken from the well location, facing west. Photo shows vegetation on well remains bare and exposed soil, or predominantly undesirable weedy plant species such as kochia/Russian thistle. Unable to find evidence that additional reclamation activities have been conducted per CAs



Photo 2: Photo taken from the well location, facing northwest. Photo shows vegetation on well remains bare and exposed soil, or predominantly undesirable weedy plant species such as kochia/Russian thistle. Unable to find evidence that additional reclamation activities have been conducted per CAs



Photo 2: Photo taken from the well location. Photo shows vegetation on well remains predominantly undesirable weedy plant species such as kochia/Russian thistle.